



HARTZELL

# PROPELLER LOGBOOK

PROPELLER MODEL HC-I3YR-1RF

PROPELLER S/N HK1176B

LOGBOOK # 1

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.																
	TSN	TSO																		
				<div style="text-align: right;">580 Airport Road, Rock Hill, SC 29732 Phone: (803) 366-5108 / Fax: (803) 366-5230</div> <div style="text-align: center;">  <p>Experience the Skytech-Advantage</p> </div> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2"><b>Propeller Log Entry</b></td> <td><b>Hobbs:</b> 328.1</td> <td><b>Registration #:</b> N614DM</td> </tr> <tr> <td><b>Date:</b> 7/17/08</td> <td></td> <td><b>Total Time:</b> 328.1</td> <td><b>Make/Model:</b> HC-I3YR-1RM</td> </tr> <tr> <td><b>W/O:</b> 63505</td> <td></td> <td><b>Cycles:</b> -----</td> <td><b>S/N:</b> HK1176B</td> </tr> <tr> <td></td> <td></td> <td><b>TSO:</b> 328.1</td> <td></td> </tr> </table> <p><b>Performed a 100 hour inspection:</b></p> <ul style="list-style-type: none"> <li>Performed 100 hour inspection on prop IAW PA-32R-301T MM Chapter 5. ADs 2008-13.</li> </ul> <p><b>Completed the following additional items:</b></p> <ul style="list-style-type: none"> <li>Lubricated prop.</li> <li>Resafetied prop bolts where previously was safetied wrong.</li> </ul> <p>I certify that this <b>PROPELLER</b> has been inspected in accordance with an <b>100-Hour</b> inspection and was determined to be in airworthy condition.</p> <p><b>MAINTENANCE RELEASE</b></p> <p>The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under <b>Work Order No: 63505 Date: July 17, 2008</b></p> <p>Signed  for Skytech, Inc., PO Box 37507, Rock Hill, SC 29732.</p> <p style="text-align: center;">CRS# C41R727N</p>	<b>Propeller Log Entry</b>		<b>Hobbs:</b> 328.1	<b>Registration #:</b> N614DM	<b>Date:</b> 7/17/08		<b>Total Time:</b> 328.1	<b>Make/Model:</b> HC-I3YR-1RM	<b>W/O:</b> 63505		<b>Cycles:</b> -----	<b>S/N:</b> HK1176B			<b>TSO:</b> 328.1	
<b>Propeller Log Entry</b>		<b>Hobbs:</b> 328.1	<b>Registration #:</b> N614DM																	
<b>Date:</b> 7/17/08		<b>Total Time:</b> 328.1	<b>Make/Model:</b> HC-I3YR-1RM																	
<b>W/O:</b> 63505		<b>Cycles:</b> -----	<b>S/N:</b> HK1176B																	
		<b>TSO:</b> 328.1																		



**Sensenich Propeller Service, Inc.**

1142 Aviation Boulevard Gainesville, Ga. 30501

Phone (770)538-0444 Fax (770)538-0117 www.sensenichpropellers.com

Date of Balance: **2/17/09**

Aircraft: **Piper PA32R-300**

Work Order Number: **G12403**

Reg. No.: **N614DM**

Propeller Serial No: **HK1176B**

Tach: **397.6**

Final Balance: **.04**

C. Neal Jones

Repair Station S46R346N

This Propeller has been balanced using procedures outlined in manual:  
Aces System to Propeller Balancing.



**Pelican Aviation, Inc. Summerville SC 29483**

11-8-11 N614DM Tach 664.9 TSN 664.9

Inspected prop for condition and security. No AD's apply at this time. Test ran OK at this time.

*At the time of this inspection, I certify that this prop has been inspected in accordance with an ANNUAL inspection and was found to be airworthy.*

*Steven F Barbieri*

Steven F Barbieri AP 3129565 IA

11-12-12 771.6

INSPECTED PROPELLER USING FAR 43.0'h AS A GUIDE. NO DISCREPANCIES

NOTED, NO AD'S APPLY AT THIS TIME - *John J Barbieri*

AD 1767223

Date 11-12-12 Total Time 771.6 Meter Time 771.6  
I certify that this PROPELLER has been inspected in  
accordance with ANNUAL inspection and was  
determined to be in air worthy condition.

John J. Barbieri 1767223 IA

*John J Barbieri*

Date

Propeller  
TSN

A/C  
Hrs

Description of all operations pertaining to Airworthiness Directives,  
Service Documents, Overhaul, Major or Minor Repair, and Inspections.



580 Airport Road, Rock Hill, SC 29732  
Phone: (803) 366-5108 / Fax: (803) 366-5230


<b>Propeller Log Entry</b>		<b>Hobbs:</b> 772.7	<b>Registration #:</b> N614DM
<b>Date:</b>	1 DEC 2012		<b>Make/Model:</b> HC-I3YR-1RM
<b>W/O:</b>	UZA-100751		<b>S/N:</b> HK1176B

- Performed AD and SB research. No AD's due at this time. Reviewed 11/27/2012
- Performed ground run-up. NDN.

**MAINTENANCE RELEASE**

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to work performed. Pertinent details of the repair are on file at this agency under Work Order No:

UZA-100751

Signed  for Skytech, Inc., PO Box 37507, Rock Hill, SC 29732.

CRS# C41R727N

PROP MODEL  
PROP S/N  
REG. NO. 614DM  
WORK ORDER:  
5818-11-2013



Premier Aircraft Service, Inc.  
5540 NW 23rd Avenue Hanger 14  
Fort Lauderdale, FL 33309  
Phone: (954) 334-2393

DATE: 12/4/2013  
A/C TSN: 980.4  
PROP TT  
TACH: 980.4

**Prop Entries**

(6) REMOVED PROP AND REINSTALLED PROP AFTER OVERHAUL IAW PIPER MM CH 61-10-00 OPS AND LEAK CHECK GOOD... (7) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PA32R-301T M/M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH CURRENT ON ATP.

I certify this propeller has been inspected in accordance with an ANNUAL inspection and found in airworthy condition on this date. Approved for return to service on this date.

DATE: 12/4/2013

SIGNED:

Sam Tavares, IA: 3521895

Work Order: 5818-11-2013

Printed by EBis 3 (datcomedia.com)

Description of all operations pertaining to Airworthiness Directives,  
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date

Propeller  
TSN TSO

A/C  
Hrs

PROP MODEL:  
HC-13YR-1RF  
PROP S/N: HK1178B  
REG. NO: 81ADM  
WORK ORDER:  
6092-05-2014



Premier Aircraft Service, Inc.

5540 NW 23rd Avenue Hanger 14  
Fort Lauderdale, FL 33309  
Phone: (954) 334-2303

DATE: 5/12/2014  
A/C TSN: 1048.7  
PROP TT: 1048.7  
HOBBS: 1048.7

TTSCH 88.3

**Prop Entries**

(5) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING PA-32r-301T M/M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED THROUGH CURRENT ON ATP.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND FOUND IN AIRWORTHY CONDITION ON THIS DATE. APPROVED FOR RETURN TO SERVICE ON THIS DATE.

DATE: 5/12/2014

SIGNED:

Work Order: 6092-05-2014

Sam Tavarez, IA: 3521895

Printed by EBis 3 (datcomedia.com)



Date: 6/14/2015

Hours: 1175.0

Tail: N614DM

Make: Hartzell

Model: HC-I3YR-1RE


Serial: HK1176B

Comments:

C/W Annual Inspection on this propeller, lubed & filed & paint. I certify that this propeller has been inspected and found to be in airworthy condition. Checked all AD'S to date. -End -

Name: Alan Pakoyk

Cert: 1580072IA

Signature: 



7/27/17

HOBBS

1333<sup>9</sup>

TT Prop 1333<sup>9</sup>

I CERTIFY THAT THIS PROP WAS INSPECTED IN ACCORDANCE WITH  
A 100 HR INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION

Mary Louise AP 2051687

PROP MODEL:  
HC-13YR-1RF  
PROP S/N: HK1176B  
REG. NO: 614DM  
WORK ORDER:  
8989-07-2020



Premier Aircraft Service, Inc.  
5540 NW 23rd Avenue Hanger 14  
Fort Lauderdale, FL 33309  
Phone: (954) 334-2393

DATE: 8/26/2020  
A/C TSN: 1682 9  
PROP TT: 1682 9  
TSPOH: 0.1  
HOBBS: 1682 9

**Prop Entries**

(4) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW 14 CFR PART 43, APPENDIX "D" USING PA32R-301T MM INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH CURRENT ON ATP.  
(21) REMOVED AND RE INSTALLED PROPELLER P/N: HC-13YR-1RF S/N: HK1176B AFTER OVERHAUL FROM PALM BEACH AIRCRAFT PROP (UNDER W/O 21189) I.A.W. PA32R-301T MM CH 61-10-00.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 8/26/2020

SIGNED:

Emmanuel Vicoso, IA: 3708718

Work Order: 8989-07-2020

Printed by EBis 3 (datcomedia.com)





